TRI-1003

SET UP INSTRUCTIONS:

- 1. CONNECT BOTTOM AND TOP TUBES FOLLOWING THE LABELS
- 2. CONNECT SIDE TUBES
- 3. CLEAN THE FRAME AND PLACE THEM ON CLEAN PLACE 4. CAREFULLY REMOVE FABRIC COVER FROM BAG
- 5. PLACE COVER AROUND THE BOTTOM OF THE FRAME
- 6. PULL COVER CAREFULLY UP TO THE TOP
- 7. CLOSE ALL ZIPPERS
- 8. ADJUST FABRIC AROUND THE FRAME
- 9. CONNECT CABLE HARNESS TO THE EYEBOLTS
- 10. COMPLETELY TIGHTEN THREADED CONNECTORS

BREAK DOWN INSTRUCTIONS:


REVERSE SET-UP STEPS TO BREAKDOWN FRAME

FABRIC CARE INSTRUCTIONS:

- 1. UNZIP COVER ZIPPERS
- 2. CAREFULLY REMOVE FABRIC COVER
- 3. CLOSE ALL ZIPPERS
- 4. FOLD OR ROLL NEATLY
- 5. PLACE FABRIC IN COVER BAG

TOTAL WEIGHT: 35.1(lbs)

MAX SIZE: 55.9(in) HARDWARE: 20.5(lbs) GRAPHIC: 12.5(lbs)



FOR CORNERS OF 3' STRUCTURES USING RIVETS FOR CORNERS TO TC-30-90T JUNCTIONS OF 3' STRUCTURES USING RIVETS	SPDR-30-S4-3 SPDR-30-S4-3 TC-30-T TRI-10-T1 TC-30-A-60 ZIPPER ZIPPER ZIPPER
ITH 1/4-20 EYE BOLT	
	·

STEP 1

STEP 2

CODE	DESCRIPTION
SPDR-30-R-3	30MM STRAIGHT SPREADER FOR CORNERS OF 3' STRUCTURES USING RIVETS
SPDR-30-S4-3	30MM STRAIGHT SPREADER FOR CORNERS TO TC-30-90T JUNCTIONS OF 3' STRUCTURES USING RIVETS
TC-30-A-60°-EYEBOLT	TC-30-A ASSEMBLED at 60° WITH 1/4-20 EYE BOLT
TC-30-A-60°	TC-30-A ASSEMBLED at 60°
TC-30-T	T JUNCTION FOR 30MM TUBING
TRI-10-T1	TUBE 1 FOR 10' TRIANGLE HANGING FABRIC STRUCTURE
	SPDR-30-R-3 SPDR-30-S4-3 TC-30-A-60°-EYEBOLT TC-30-A-60° TC-30-T



