
<u>exhibitline</u>

Steps 1&2. Attach extrusions to canopy using 2 **long** knobs per extrusion. Attach canopy haves using black plastic latches. Insert 1 **long** knob as shown in lower left.



Steps 3&4. Insert plex w/ pre-installed puck lights. Attach one 3-way power splitter to left 3 lights and one to right 3 lights.



Steps 5&6. Attach left and right lower columns to feet using 2 **short** knobs per column. Install gusset caps.



Steps 7&8. Attach left and right lower columns to upper columns using 2 **short** knobs.




Step 9. Connect upper and lower graphic hangers. Slide upper and lower graphic hangers into graphic and hang graphic. Use metal slides to apply slight downward pressure on lower graphic hanger.




Step 10. Slide canopy supports onto columns and tighten **short** knobs. Place canopy onto supports.











exhibitline

Step 13-15. Attach left counter to left column using one **long** knob. Join counters using two **long** knobs and plastic joining plate. Use one **long** knob to attach center counter leg.



Steps 16-18. Attach header to canopy using standoff heads. Attach wings to grippers, tighten thumb knobs. Insert infill panels.



