



Steps:

- 1) Slide Infill between verticals of stand.
- 2) Attach horizontal extrusion between stand verticals.
- 3) Attach base plate to bottom of stand verticals, using bolts.
- 4) Attach plate to top end of stand, using bolt.

NOTE: Plate must rotate left and right, before installing clamshell.

- 5) Attach clamshell to plate, using hex nuts.
- 6) Insert iPad in clamshell and feed cord through holes. See Cord Management For iPad detail.
- 7) Attach literature holders to stand where desired. See Literature Holder detail.






Clamshell


Nuts






- 1) Remove foam lining from inside bottom of clamshell.
- 2) Attach Home Button Shield with double-sided tape to inside of clamshell, keeping top of shield flush with clamshell opening.

NOTE: This is a permanent fix and can't be easily removed.



Completed Assembly

Cord Management For iPad





Attach iPad cord to supplied USB extension cord. Feed USB cord through top hole of post, then out bottom hole of post. connect to power.

SETUP INSTRUCTIONS

General Information

General Setup Instructions


- Read entire setup instruction manual prior to unpacking parts and pieces.
- The setup instructions are created specifically for this configuration.
- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.

Cleaning & Packing


- For Cleaning Metal, Plex, & Laminate Parts: Use a MILD NON-ABRASIVE cleanser and soft cloth/paper towel to clean all surfaces.
- Keep exhibit components away from heat and prolonged sun exposure. Heat and UV exposure will warp and fade components.
- Retain all provided Packing Materials. All provided packing materials are for ease of repacking & component protection.

Disassembly

- For loss prevention, tighten all setscrews and locks during disassembly



Hex Tool - Essential for Assembly




Part Identification - Numbering




DO NOT USE POWER TOOLS

MARNING




Spline Connection




Base Plate & Extrusion Connection



LADDERS OR LIFTS MAY BE REQUIRED



Extrusion & Lock Connection




Engaged Lock




ALL CONNECTIONS MUST BE TIGHTLY SECURED



Top View of Each Level





Setup Hardware with (2) Literature Holders