
<u>exhibitline</u>

Steps 1-3. Attach extrusions to canopy using 2 **long** knobs per extrusion. Attach canopy halfs using black plastic latches. Attach standoffs. Insert 1 **long** knob as shown in lower left.



Step 4. Insert plex w/ pre-installed puck lights. Attach one 3-way power splitter to left 3 lights and one to right 3 lights.




Steps 5&6. Attach left and right lower columns to feet using 2 **short** thumb knobs per column. Install gusset caps.



Steps 7&8. Attach left and right lower columns to upper columns using 2 **short** thumb knobs.



Step 9. Connect upper and lower graphic hangers. Slide upper and lower graphic hangers into graphic and hang graphic.



Step 10. Slide canopy supports onto columns and tighten **short** knobs. Place canopy onto supports.



Step 11. Attach counter legs to counters using 2 **long** knob per leg.



Step 12. Attach counters to backwall using 1 **long** knob per counter. Attach wings using **nylon tipped** knobs. Attach header using metal standoffs.

